

Water Testing Results - Myrtle Crest Elementary

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Middle Wing West	6091206-01	9/8/2016	ND
Sof. Faucet East	6091206-02	9/8/2016	0.004
South West Drinking Fountain	6091206-03	9/8/2016	ND
Staff Lounge	6091206-04	9/8/2016	ND
Conference Room Faucet	6091206-05	9/8/2016	ND
Girls' Gym Fountain	6091206-08	9/8/2016	ND
Kitchen Sink 2	6091206-10	9/8/2016	ND
Band Room Fountain	6091206-11	9/8/2016	0.006
Spicket on Back Alley Road	6091206-12	9/8/2016	0.017
Kitchen Sink 1	6091206-13	9/8/2016	ND
Room 6	6091206-15	9/8/2016	ND
Room 3	6091206-25	9/8/2016	ND
Middle Wing Drinking Fountain	6091206-26	9/8/2016	ND

Water Testing Results - Myrtle Point High School

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Breezeway Fountain	6091206-06	9/8/2016	0.028
Staff Lounge	6091206-07	9/8/2016	ND
Main Fountain Across From Office	6091206-09	9/8/2016	ND
Agg Kitchen Fountain	6091206-14	9/8/2016	ND
Girls' Locker Room Fountain	6091206-16	9/8/2016	0.019
kitchen	6091206-17	9/8/2016	0.009
Old Wing Fountain	6091206-18	9/8/2016	0.004
2nd Floor Fountain	6091206-19	9/8/2016	ND
Gym Fountain	6091206-20	9/8/2016	ND
A4	6091206-21	9/8/2016	0.005
Boys' Locker Room Fountain	6091206-22	9/8/2016	0.002

Cafeteria Fountain	6091206-23	9/8/2016	0.009
R.O.S. Fountain	6091206-24	9/8/2016	0.014
A5	6091206-27	9/8/2016	0.007